



Guiding Clamp FZ02/3 Standard

Robust and accurate for V-belts up to profile 32 (D) and round belts from Ø 8 mm.



Paddle for SG02 / SG03

Spare paddle for welding tools SG02 & SG03 Standard. Dimensions (HxWxD): 35 x 35 x 2 mm.



V-Belt Pulley Groove Gauge

To control wear in grooves SPZ, SPA, SPB and SPC.



Guide Clamp FZ01

Handy and lightweight for round belts up to Ø 10 mm and V-belts up to profile 10 (Z).

Welding Set:

- 1 pc scissors AS02
- 2 pc Guide clamps FZ01
- 1 pc Edge cutter SE02
- 1 pc Carrying bag LxBxH 31x20x5 cm
- 1 pc ergo paddle welding tool (PU and TPE)

Electronic Measurement of Belt Tension

VSM 1 (10-500 hz) and VSM 3 (5-500 hz) are electronic measuring instruments that have been specially designed to measure the initial tension of timing belts, poly-V-belts and V-belts.

Friction Welding Machine RS02

- Scope of delivery:
- 1 pc. Friction welding machine RS02
 - 1 set standard profile jaws at your choice
 - 1 pc. Torque wrench
 - 1 pc. Scissors AS02
 - 1 pc. Edge cutter SE02
 - 1 pc. Carrying case with durable and protective foam inlay

Scissors

AS02 scissors small with stop 90° cut for round belts up to Ø12 mm.

Measuring Gauge

The measuring gauge ensures the reliable measurement of V-belts and multi V-belts. Range up to 2500mm.

For more information regarding Tools for belt drives [click here.](#)